



PT Expressindo 88 Nusantara

Pergudangan Indo Pangan, Karawang Barat, Karawang, Jawa Barat

www.e88group.com

Product of PT Haier Sales Indonesia

Inbound List

| | | | |
|------------|-----------------------|--------------|--------------|
| ID Inbound | : IB-000774 | Truck Number | : B 9198 JXR |
| Date | : 2025-02-26 17:11:21 | Driver Name | : AEP |
| Location | : CDC5 Good Set | Status | : OPEN U63 |

Product Items

| No | Serial | Model | QTY |
|----|-----------|--------------|------------|
| 1 | TD0042756 | AQF-980GC | 1 |
| 2 | TD0042755 | AQF-600GC | 2 |
| 3 | DH1VYF050 | AQT43K80FX | 90 |
| 4 | DH1VL3050 | AQT50K800UX | 25 |
| 5 | DH1U6G050 | AQT32K70M | 98 |
| 6 | B30JU7E00 | AQF-550EC | 2 |
| | | Total | 218 |

Serial Number IB-000774 | B 9198 JXR

| No | Serial Number | Model | No | Serial Number | Model |
|----|----------------------|-----------|-----|----------------------|------------|
| 1 | DH1U6G050010PQCP0645 | AQT32K70M | 51 | DH1U6G050010PQCP0646 | AQT32K70M |
| 2 | DH1U6G050010PQCP0590 | AQT32K70M | 52 | DH1U6G050010PQCP0664 | AQT32K70M |
| 3 | DH1U6G050010PQCP0573 | AQT32K70M | 53 | DH1U6G050010PQCP0731 | AQT32K70M |
| 4 | DH1U6G050010PQCP0659 | AQT32K70M | 54 | DH1U6G050010PQCP1591 | AQT32K70M |
| 5 | DH1U6G050010PQCP0575 | AQT32K70M | 55 | DH1U6G050010PQCP1566 | AQT32K70M |
| 6 | DH1U6G050010PQCP0583 | AQT32K70M | 56 | DH1U6G050010PQCP0676 | AQT32K70M |
| 7 | DH1U6G050010PQCP0580 | AQT32K70M | 57 | DH1U6G050010PQCP1598 | AQT32K70M |
| 8 | DH1U6G050010PQCP0568 | AQT32K70M | 58 | DH1U6G050010PQCP2016 | AQT32K70M |
| 9 | DH1U6G050010PQCP0565 | AQT32K70M | 59 | DH1U6G050010PQCP0740 | AQT32K70M |
| 10 | DH1U6G050010PQCP0567 | AQT32K70M | 60 | DH1U6G050010PQCP0669 | AQT32K70M |
| 11 | DH1U6G050010PQCP0569 | AQT32K70M | 61 | DH1U6G050010PQCP2039 | AQT32K70M |
| 12 | DH1U6G050010PQCP0732 | AQT32K70M | 62 | DH1U6G050010PQCP1594 | AQT32K70M |
| 13 | DH1U6G050010PQCP0586 | AQT32K70M | 63 | DH1VYF050020PQCQ0847 | AQT43K80FX |
| 14 | DH1U6G050010PQCP0563 | AQT32K70M | 64 | DH1VYF050020PQCQ0731 | AQT43K80FX |
| 15 | DH1U6G050010PQCP0605 | AQT32K70M | 65 | DH1VYF050020PQCQ0705 | AQT43K80FX |
| 16 | DH1U6G050010PQCP0579 | AQT32K70M | 66 | DH1VYF050020PQCQ0752 | AQT43K80FX |
| 17 | DH1U6G050010PQCP0736 | AQT32K70M | 67 | DH1VYF050020PQCQ0912 | AQT43K80FX |
| 18 | DH1U6G050010PQCP0729 | AQT32K70M | 68 | DH1VYF050020PQCQ0706 | AQT43K80FX |
| 19 | DH1U6G050010PQCP0588 | AQT32K70M | 69 | DH1VYF050020PQCQ0744 | AQT43K80FX |
| 20 | DH1U6G050010PQCP0600 | AQT32K70M | 70 | DH1VYF050020PQCQ1448 | AQT43K80FX |
| 21 | DH1U6G050010PQCP0598 | AQT32K70M | 71 | DH1VYF050020PQCQ0494 | AQT43K80FX |
| 22 | DH1U6G050010PQCP0587 | AQT32K70M | 72 | DH1VYF050020PQCQ0503 | AQT43K80FX |
| 23 | DH1U6G050010PQCP0570 | AQT32K70M | 73 | DH1VYF050020PQCQ0505 | AQT43K80FX |
| 24 | DH1U6G050010PQCP0585 | AQT32K70M | 74 | DH1VYF050020PQCQ0726 | AQT43K80FX |
| 25 | DH1U6G050010PQCP0582 | AQT32K70M | 75 | DH1VYF050020PQCQ0857 | AQT43K80FX |
| 26 | DH1U6G050010PQCP0594 | AQT32K70M | 76 | DH1VYF050020PQCQ0856 | AQT43K80FX |
| 27 | DH1U6G050010PQCP0566 | AQT32K70M | 77 | DH1VYF050020PQCQ0753 | AQT43K80FX |
| 28 | DH1U6G050010PQCP0581 | AQT32K70M | 78 | DH1VYF050020PQCQ0751 | AQT43K80FX |
| 29 | DH1U6G050010PQCP0654 | AQT32K70M | 79 | DH1VYF050020PQCQ0754 | AQT43K80FX |
| 30 | DH1U6G050010PQCP0584 | AQT32K70M | 80 | DH1VYF050020PQCQ0852 | AQT43K80FX |
| 31 | DH1U6G050010PQCP0572 | AQT32K70M | 81 | DH1VYF050020PQCQ0711 | AQT43K80FX |
| 32 | DH1U6G050010PQCP0577 | AQT32K70M | 82 | DH1VYF050020PQCQ0839 | AQT43K80FX |
| 33 | DH1U6G050010PQCP0574 | AQT32K70M | 83 | DH1VYF050020PQCQ0727 | AQT43K80FX |
| 34 | DH1U6G050010PQCP0653 | AQT32K70M | 84 | DH1VYF050020PQCQ0756 | AQT43K80FX |
| 35 | DH1U6G050010PQCP0606 | AQT32K70M | 85 | DH1VYF050020PQCQ1340 | AQT43K80FX |
| 36 | DH1U6G050010PQCP1146 | AQT32K70M | 86 | DH1VYF050020PQCQ1330 | AQT43K80FX |
| 37 | DH1U6G050010PQCP0759 | AQT32K70M | 87 | DH1VYF050020PQCQ0880 | AQT43K80FX |
| 38 | DH1U6G050010PQCP0684 | AQT32K70M | 88 | DH1VYF050020PQCQ0879 | AQT43K80FX |
| 39 | DH1U6G050010PQCP0595 | AQT32K70M | 89 | DH1VYF050020PQCQ0867 | AQT43K80FX |
| 40 | DH1U6G050010PQCP1154 | AQT32K70M | 90 | DH1VYF050020PQCQ0883 | AQT43K80FX |
| 41 | DH1U6G050010PQCP0656 | AQT32K70M | 91 | DH1VYF050020PQCQ0875 | AQT43K80FX |
| 42 | DH1U6G050010PQCP1157 | AQT32K70M | 92 | DH1VYF050020PQCQ0865 | AQT43K80FX |
| 43 | DH1U6G050010PQCP0683 | AQT32K70M | 93 | DH1VYF050020PQCQ1331 | AQT43K80FX |
| 44 | DH1U6G050010PQCP0578 | AQT32K70M | 94 | DH1VYF050020PQCQ0876 | AQT43K80FX |
| 45 | DH1U6G050010PQCP0660 | AQT32K70M | 95 | DH1VYF050020PQCQ1328 | AQT43K80FX |
| 46 | DH1U6G050010PQCP0757 | AQT32K70M | 96 | DH1VYF050020PQCQ0881 | AQT43K80FX |
| 47 | DH1U6G050010PQCP0602 | AQT32K70M | 97 | DH1VYF050020PQCQ1335 | AQT43K80FX |
| 48 | DH1U6G050010PQCP0647 | AQT32K70M | 98 | DH1VYF050020PQCQ0884 | AQT43K80FX |
| 49 | DH1U6G050010PQCP0672 | AQT32K70M | 99 | DH1VYF050020PQCQ1345 | AQT43K80FX |
| 50 | DH1U6G050010PQCP0662 | AQT32K70M | 100 | DH1VYF050020PQCQ0838 | AQT43K80FX |

Serial Number IB-000774 | B 9198 JXR

| No | Serial Number | Model | No | Serial Number | Model |
|-----|----------------------|------------|-----|----------------------|-------------|
| 101 | DH1VYF050020PQCQ0843 | AQT43K80FX | 151 | DH1U6G050010PQCP0657 | AQT32K70M |
| 102 | DH1VYF050020PQCQ0916 | AQT43K80FX | 152 | DH1U6G050010PQCP2836 | AQT32K70M |
| 103 | DH1VYF050020PQCQ0708 | AQT43K80FX | 153 | DH1U6G050010PQCP2835 | AQT32K70M |
| 104 | DH1VYF050020PQCQ0710 | AQT43K80FX | 154 | DH1U6G050010PQCP2840 | AQT32K70M |
| 105 | DH1VYF050020PQCQ0492 | AQT43K80FX | 155 | DH1U6G050010PQCP2057 | AQT32K70M |
| 106 | DH1VYF050020PQCQ0501 | AQT43K80FX | 156 | DH1U6G050010PQCP2072 | AQT32K70M |
| 107 | DH1VYF050020PQCQ0496 | AQT43K80FX | 157 | DH1U6G050010PQCP2808 | AQT32K70M |
| 108 | DH1VYF050020PQCQ0493 | AQT43K80FX | 158 | DH1U6G050010PQCP2823 | AQT32K70M |
| 109 | DH1VYF050020PQCQ0495 | AQT43K80FX | 159 | DH1U6G050010PQCP1570 | AQT32K70M |
| 110 | DH1VYF050020PQCQ0513 | AQT43K80FX | 160 | DH1U6G050010PQCP1575 | AQT32K70M |
| 111 | DH1VYF050020PQCQ0481 | AQT43K80FX | 161 | DH1U6G050010PQCP2839 | AQT32K70M |
| 112 | DH1VYF050020PQCQ0021 | AQT43K80FX | 162 | DH1U6G050010PQCP2828 | AQT32K70M |
| 113 | DH1VYF050020PQCQ0015 | AQT43K80FX | 163 | DH1U6G050010PQCP2825 | AQT32K70M |
| 114 | DH1VYF050020PQCQ0502 | AQT43K80FX | 164 | DH1U6G050010PQCP2829 | AQT32K70M |
| 115 | DH1VYF050020PQCQ0498 | AQT43K80FX | 165 | DH1U6G050010PQCP2824 | AQT32K70M |
| 116 | DH1VYF050020PQCQ0512 | AQT43K80FX | 166 | DH1U6G050010PQCP2067 | AQT32K70M |
| 117 | DH1VYF050020PQCQ0725 | AQT43K80FX | 167 | DH1U6G050010PQCP2809 | AQT32K70M |
| 118 | DH1VYF050020PQCQ0497 | AQT43K80FX | 168 | DH1U6G050010PQCP2022 | AQT32K70M |
| 119 | DH1VYF050020PQCQ0504 | AQT43K80FX | 169 | DH1U6G050010PQCP1585 | AQT32K70M |
| 120 | DH1VYF050020PQCQ0027 | AQT43K80FX | 170 | DH1U6G050010PQCP1593 | AQT32K70M |
| 121 | DH1VYF050020PQCQ0022 | AQT43K80FX | 171 | DH1U6G050010PQCP2815 | AQT32K70M |
| 122 | DH1VYF050020PQCQ0010 | AQT43K80FX | 172 | DH1U6G050010PQCP2076 | AQT32K70M |
| 123 | DH1VYF050020PQCQ0018 | AQT43K80FX | 173 | DH1U6G050010PQCP1569 | AQT32K70M |
| 124 | DH1VYF050020PQCQ0020 | AQT43K80FX | 174 | DH1U6G050010PQCP2826 | AQT32K70M |
| 125 | DH1VYF050020PQCQ0012 | AQT43K80FX | 175 | DH1U6G050010PQCP2843 | AQT32K70M |
| 126 | DH1VYF050020PQCQ0510 | AQT43K80FX | 176 | DH1U6G050010PQCP2830 | AQT32K70M |
| 127 | DH1VYF050020PQCQ0025 | AQT43K80FX | 177 | DH1U6G050010PQCP1571 | AQT32K70M |
| 128 | DH1VYF050020PQCQ0760 | AQT43K80FX | 178 | DH1U6G050010PQCP2837 | AQT32K70M |
| 129 | DH1VYF050020PQCQ0769 | AQT43K80FX | 179 | DH1U6G050010PQCP2068 | AQT32K70M |
| 130 | DH1VYF050020PQCQ0755 | AQT43K80FX | 180 | DH1U6G050010PQCP2040 | AQT32K70M |
| 131 | DH1VYF050020PQCQ0855 | AQT43K80FX | 181 | DH1U6G050010PQCP2842 | AQT32K70M |
| 132 | DH1VYF050020PQCQ0745 | AQT43K80FX | 182 | DH1VYF050020PQCQ0887 | AQT43K80FX |
| 133 | DH1VYF050020PQCQ0842 | AQT43K80FX | 183 | DH1VYF050020PQCQ1329 | AQT43K80FX |
| 134 | DH1VYF050020PQCQ0026 | AQT43K80FX | 184 | DH1VYF050020PQCQ0878 | AQT43K80FX |
| 135 | DH1VYF050020PQCQ0859 | AQT43K80FX | 185 | DH1VYF050020PQCQ1338 | AQT43K80FX |
| 136 | DH1VYF050020PQCQ0707 | AQT43K80FX | 186 | DH1VYF050020PQCQ0874 | AQT43K80FX |
| 137 | DH1VYF050020PQCQ0704 | AQT43K80FX | 187 | DH1VYF050020PQCQ0863 | AQT43K80FX |
| 138 | DH1VYF050020PQCQ0759 | AQT43K80FX | 188 | DH1VYF050020PQCQ1248 | AQT43K80FX |
| 139 | DH1VYF050020PQCQ0858 | AQT43K80FX | 189 | DH1VYF050020PQCQ1350 | AQT43K80FX |
| 140 | DH1VYF050020PQCQ0913 | AQT43K80FX | 190 | DH1VYF050020PQCQ1342 | AQT43K80FX |
| 141 | DH1VYF050020PQCQ0886 | AQT43K80FX | 191 | DH1VL3050010PR1Q0049 | AQT50K800UX |
| 142 | DH1VYF050020PQCQ0779 | AQT43K80FX | 192 | DH1VL3050010PR1Q0618 | AQT50K800UX |
| 143 | TD004275500F2QCF0057 | AQF-600GC | 193 | DH1VL3050010PR1Q0609 | AQT50K800UX |
| 144 | B30JU7E00039BQCV0189 | AQF-550EC | 194 | DH1VL3050010PR1Q0088 | AQT50K800UX |
| 145 | B30JU7E00039BQCV0146 | AQF-550EC | 195 | DH1VL3050010PR1Q0563 | AQT50K800UX |
| 146 | DH1U6G050010PQCP1584 | AQT32K70M | 196 | DH1VL3050010PR1Q0810 | AQT50K800UX |
| 147 | DH1U6G050010PQCP1578 | AQT32K70M | 197 | DH1VL3050010PR1Q0816 | AQT50K800UX |
| 148 | DH1U6G050010PQCP1583 | AQT32K70M | 198 | DH1VL3050010PR1Q0819 | AQT50K800UX |
| 149 | DH1U6G050010PQCP1574 | AQT32K70M | 199 | DH1VL3050010PR1Q0809 | AQT50K800UX |
| 150 | DH1U6G050010PQCP0589 | AQT32K70M | 200 | DH1VL3050010PR1Q0611 | AQT50K800UX |

Serial Number IB-000774 | B 9198 JXR

| No | Serial Number | Model | No | Serial Number | Model |
|-----|----------------------|-------------|----|---------------|-------|
| 201 | DH1VL3050010PR1Q0617 | AQT50K800UX | | | |
| 202 | DH1VL3050010PR1Q0560 | AQT50K800UX | | | |
| 203 | DH1VL3050010PR1Q0806 | AQT50K800UX | | | |
| 204 | DH1VL3050010PR1Q0566 | AQT50K800UX | | | |
| 205 | DH1VL3050010PR1Q0087 | AQT50K800UX | | | |
| 206 | DH1VL3050010PR1Q0561 | AQT50K800UX | | | |
| 207 | DH1VL3050010PR1Q0622 | AQT50K800UX | | | |
| 208 | TD004275600F2QBL0044 | AQF-980GC | | | |
| 209 | TD004275500F2QCF0012 | AQF-600GC | | | |
| 210 | DH1VYF050020PQCQ1229 | AQT43K80FX | | | |
| 211 | DH1VL3050010PR1Q0823 | AQT50K800UX | | | |
| 212 | DH1VL3050010PR1Q0797 | AQT50K800UX | | | |
| 213 | DH1VL3050010PR1Q0621 | AQT50K800UX | | | |
| 214 | DH1VL3050010PR1Q0613 | AQT50K800UX | | | |
| 215 | DH1VL3050010PR1Q0817 | AQT50K800UX | | | |
| 216 | DH1VL3050010PR1Q0818 | AQT50K800UX | | | |
| 217 | DH1VL3050010PR1Q0610 | AQT50K800UX | | | |
| 218 | DH1VL3050010PR1Q0608 | AQT50K800UX | | | |